

TECHNICAL INFORMATION

Washing machines and dryers

4-023-1231

MODIFICATION ON CONTROL UNIT - DIFFERENT IONIZER CONNECTION

Removed connector from the main board - different ionizer connection.

Control unit before changes.



Control unit after changes - removed connector for ionizer and steam generator.



Removed connector (for ionizer and steam generator) from the main board. - different ionizer connection.

New situation

Ionizer is powered by the pump, it is necessary to replace the pump wiring set.

Old wiring set for the pump and the ionizer is eliminated.


For teh control units:

- 345074,
- 389536,
- 367228,
- 348914,
- 393532,
- 391783,

replace cable set 334656 and install 393294.

And eliminate cable set for the ionizer code 347600.

Connect the ionizer through the pump.



3

4

5